



図7 原子炉容器上蓋に見つかった腐食劣化の状況(スケッチ)

[出典]NRC Davis-Besse Lessons Learned Task Force, "Davis-Besse Reactor Vessel Head Degradation Lessons-Learned Task Force Report," September 30, 2002 (pp.17)

<http://www.nrc.gov/reactors/operating/ops-experience/vessel-head-degradation/vessel-head-degradation-files/db-nozzle3-degr-sketch.pdf>